

» PARTS

» SOCIAL

» BLOG

» HELP

» ABOUT

CUSCO LANCER (CE9A) FOR REAR UPPER ARM



» Used Parts

» Worldwide Shipping



Used product descriptions are machine translated, contact us to confirm product details.

CD5A, CD9A CE9A for Lancer made in Cusco rear upper arm left and right set adjustment range: + 12 mm-12 mm steel side Provo, one side rubber Bush corrected to proper camber angle, improve the erratic behavior! And straightening the camber angle of the rear ride height changes in the TURNBUCKLE adjustment rear, firmly improve the grounding and traction on Undulated road surfaces! Body, manual included.

A little rust and paint adhesion, but fixation tuning parts. No Pyro slack! No Bush jole! In you are looking for!

- » Vehicle Model: CD5A/CD9A/CE9A
- » Model: 510 474 L

» Cusco Website

VERSION

IP-2985356
Lancer (CE9A) for rear upper arm - 10-41791

PRICE ORDER

SOLD